

Scott M. Matheson, Governor Temple A. Reynolds, Executive Director Cleon B. Feight, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

July 8, 1982

D. M. Mercier
Banquest Resources, Ltd.
650 - 409 Granville Street
Vancouver, B.C.
Canada U6C 1T2

RE: Urango Mining Co. ACT/017/012

Garfield County, Utah

Dear Mr. Mercier:

The attached material was recently returned to our office marked undeliverable at the address sent. Therefore, the Division has no way of reaching Mr. Sawyer other than through you. Apparently his address is no longer at:

Sawyer Consultants, Inc. 1-425 Howe Street Vancouver, B.C. V6C 2A9 Canada

Would you please forward this on to your contractor? In addition, what is the status of your reply to the information requested over the phone on June 1, 1982? (i.e. formal suspension notice for mining activity) The Division will await your earliest reply.

Sincerely yours,

THOMAS N. TETTING ENGINEERING GEOLOGIST

Enclosure

TNT:dc



Scott M. Matheson, Governor Temple A. Reynolds, Executive Director Cleon B. Feight, Division Director

4241 State Office Building · Salt Lake City, UT 84114 · 801-533-5771

June 15, 1982

Mr. J.B. Paul Sawyer Sawyer Consultants, Inc. 1-425 Howe St. Vancouver B.C. V6C 2A9

RE: Urango Mining Co.
ACT/017/012
Garfield County, Utah

Dear Mr. Sawyer:

The Division is in receipt of your letter dated June 1, 1982 and is pleased to note that you have been advised of our concerns. The most recent communication I have on file for you is a memo dated April 26, 1979. It discusses your visit during which time you were informed about the notice you would need to submit for exploration in the future. In addition, a letter was also sent to you explaining that any future mining activity should be preceded by the submittal of an updated mining and reclamation plan for the Division's review. Additionally, the most recent communication from Chinook Construction, Ltd. came in August of 1978. They committed to advising the Division of additional drilling and also to reclaiming as approved by our staff. Chinook was instructed to notify our office when drilling and reclamation were completed. They have not as yet contacted our office. Therefore, because of your apparent responsibility in that matter, I would like to request that you submit notice of the condition of the site area in response to rules M-3(5) and M-8 of the Mined Land Reclamation Act, Title 40-8, U.C.A., 1953. Please make specific mention of the current status of vegetative growth, i.e. the reestablished reseeded areas (%) vs. the undisturbed portions of the property. Also please make note of the January changes to the Rule M-3(5) which is enclosed for your information.

Based upon receipt of this information and the prior requested material needed from David Mercier, the Division's files will be brought up to date and unless further activity is planned will be satisfied after a possible inspection visit this summer. Again, thank you for the recent update and I hope to hear from you soon.

Since ely yours

THOMAS N. TETTING

ENGINEERING GEOLOGIST

cc: John Blake, State Lands D.M. Mercier

TNT:dc